

## BUILDING SAFETY CERTIFICATE

No.

Dated:

Certified that the existing building of Dayanand Public School, Shimla (name of the building or premises) at Near, SDI Main Branch, Kalu Ban' sports (address) comprised of 2 basement(s) and 2 (upper floors) owned/occupied by Principal, Dayanand Public School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of K.P.P.W.D (Name of Department/ Govt.) on 30th May 2023 (date of inspection) in the presence of as per the Building Safety Certificate (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes (X/ XII) with effect from 30th May 2023 for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Building Safety Certificate under rule 2538-39 of 19-05-2021
- 2.
- 3.
- 4.

Issued on 30th May 2023 at Shimla by

\* Strike out whichever is not applicable.

Signature with Seal: \_\_\_\_\_

Name: \_\_\_\_\_

Designation: \_\_\_\_\_

Name &amp; Address of Department: \_\_\_\_\_

(Assistant Engineer & above officer of concerned Govt. Department only)

**Note:** This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

Himachal Pradesh  
Public Works Department  
\*\*\*\*\*


No. SD-III-CB-WA- Structure Stability/2023-2538-39 Dated 19-5-23  
To

The Principal,  
Dayanand Public School,  
The mall, Shimla-171003.


Subject: Structure Stability Certificate pertaining to Dayanand Public School Shimla for the financial year 2023-24.

Reference:- Your office letter No.DPSS/Bldg/23-33 dated 8.5.2023.

In this context, it is certified that as per the report submitted by the concerned Assistant Engineer, that the inspection of Dayanand Public School Shimla was conducted by the concerned junior Engineer on 19.5.2023 and observed that the building visually seems to be safe. However, the structure stability of the said building cannot be ascertained due to non-availability of structural drawings. This certificate is being issued for the year 2023-24 purely on the basis of visual inspection and issuance of this certificate does not confirm any legal rights.

  
Executive Engineer,  
Shimla Division No.III,  
HPPWD, Shimla-3.

Copy forwarded to the Assistant Engineer, Shimla Sub-Division No. VII, HP.PWD.Shimla-3 w.r.t. his office letter No. 142 dated 19.5.2023 for information.

  
Executive Engineer,  
Shimla Division No.III,  
HPPWD., Shimla-3.